BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. :

Date : _____

1. Customer's Name and Address with Telephone No. : AEE Byatarayanapura SCs div Dasarahalli. Bangalore-24

2. Well Location : Rachenahalli. Nag floor mill

3. Total Well Depth / Drilled in Ft. : 1213 ft

4. Casing Erected in Ft. : 150 ft

5. Water Struck at the Depth of : 1100 ft, 1200 ft

6. Total Yield (Measuring method "V" Norch : 25 mtrs / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clay

8. At the Depth of : 1213 ft.

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or whatso ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Manager / Proprietor

Party's Signature

Scanned by CamScanner

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. :

Date : _____

1. Customer's Name and Address with Telephone No. : AEE KSP Sub division Dasarahalli K'Town

2. Well Location : Fathima layout - Near Muslim Hostle

3. Total Well Depth / Drilled in Ft. : 1130. ft

4. Casing Erected in Ft. : 160 ft

5. Water Struck at the Depth of : 950 ft 1090 ft

6. Total Yield (Measuring method "V" Norch : 2.5 inch / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clear

8. At the Depth of : 1130 ft

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Manager / Proprietor

Party's Signature

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. :

Date : _____

1. Customer's Name and Address with Telephone No. : AEE KEP Sub division Dasarahalli K'lok - 24

2. Well Location : Anjanadri Layout Near Ali Mazid

3. Total Well Depth / Drilled in Ft. : 1065 ft

4. Casing Erected in Ft. : 205 ft

5. Water Struck at the Depth of : Final ~~Depth~~ , ~~1065~~ ft

6. Total Yield (Measuring method "V" Norch : _____ / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clay

8. At the Depth of : 1065 ft

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Manager / Proprietor

Party's Signature

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. :

Date : _____

1. Customer's Name and Address with Telephone No. : AEE KTP SCS division Dasarahalli Division

2. Well Location : Anjanadri Layout near Hoppar mandi

3. Total Well Depth / Drilled in Ft. : 1250 ft

4. Casing Erected in Ft. : 215 ft

5. Water Struck at the Depth of : ~~250 ft~~ failed

6. Total Yield (Measuring method "V" Norch : Nil well / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clear

8. At the Depth of : 1250 ft.

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Scanned by CamScanner

Sri. Beereshwara Sawmy Prasanna

Sri. Chikkanna. C
Mob : 91415 94797
86180 32693

Cauvery Ground Water Consultant

7, 1st Main, 7th Cross, L.D Block, Ganganagar, Bangalore - 560032

Ref. :..... Date : .....

REPORT ON GROUND WATER INVESTIGATION

Name AEE KTJ Sub division

Address Byatarayanapura Sub division Dasarahalli

Location Rachenahalli.. Near flour mill

Topography —

Rock Type Clay

Soil Type Clay

Depth 385 mts

Yield 2.5

Casing 55 mts

Aqufers —

Remarks

Note : The Survey was carries out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ ಸಂರಕ್ಷಿಸಿ.... Water is precious, Conserve it.... ಗಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ....

SAVE WATER

For KAVERI BOREWELL WATER DIVINER
Sri. Chikkanna. C
CHIKKANNA.C
Water Diviner

Scanned by CamScanner

Sri. Beereshwara Sawmy Prasanna

Sri. Chikkanna. C
Mob : 91415 94797
86180 32693

Cauvery Ground Water Consultant

7, 1st Main, 7th Cross, L.D Block, Ganganagar, Bangalore - 560032

Ref. :..... Date : .....

REPORT ON GROUND WATER INVESTIGATION

Name AEE KP sas division

Address Dasarahalli K'lon-24

Location Fathima Layout near Muslim Mohalla

Topography —

Rock Type Clay

Soil Type Clay

Depth 360 mty

Yield 2.5 inch

Casing 55 mtr

Aquifers —

Remarks —

Note : The Survey was carries out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ ಸಂರಕ್ಷಿಸಿ.... Water is precious, Conserve it.... ಗಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ....

SAVE WATER

For KAVERI BOREWELL WATER DIVINER

Sri. Chikkanna. C

Chikkanna.C

Water Diviner

Scanned by CamScanner

Sri. Beereshwara Sawmy Prasanna

Sri. Chikkanna. C
Mob : 91415 94797
86180 32693

Cauvery Ground Water Consultant

7, 1st Main, 7th Cross, L.D Block, Ganganagar, Bangalore - 560032

Ref. :..... Date : .....

REPORT ON GROUND WATER INVESTIGATION

Name AEE KTJ Sub division

Address Dasarahalli Bangalore - 560024

Location Anjanadri Layout near Ali mosque

Topography —

Rock Type Clay

Soil Type Clay

Depth 350 mts

Yield 2 inch

Casing 65 mts

Aqufers —

Remarks —

Note : The Survey was carries out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ ಸಂರಕ್ಷಿಸಿ.... Water is precious, Conserve it.... ಗಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ....

SAVE WATER

For KAVERI BOREWELL WATER DIVINER
Sri. Chikkanna. C
CHIKKANNA.C
Water Diviner

Scanned by CamScanner

Sri. Beereshwara Sawmy Prasanna

Sri. Chikkanna. C
Mob : 91415 94797
86180 32693

Cauvery Ground Water Consultant

7, 1st Main, 7th Cross, L.D Block, Ganganagar, Bangalore - 560032

Ref. :..... Date : .....

REPORT ON GROUND WATER INVESTIGATION

Name AEE KIP Sub division

Address Dasarahalli. N/04-24

Location Anjanadri Layout - Near Amar masjid

Topography —

Rock Type Clay

Soil Type Clay

Depth 395 mty

Yield 2.5 inch

Casing 6T mty

Aquifers —

Remarks —

Note: The Survey was carries out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ ಸಂರಕ್ಷಿಸಿ.... Water is precious, Conserve it.... ನಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ....

SAVE WATER

For KAVERI BOREWELL WATER DIVINER

Sri. Chikkanna. C

Water Diviner

CHIKKANNA.C

Scanned by CamScanner